




Repairs to engine exhaust manifolds and sections cracked bolt hole locations... flange fractures... Corroded joint faces.



Gas fusion repair with identical material to parent metal



12 month Warranty



Classification Certification