

Heritage restoration Harewood House Gates

Harewood House, Leeds is home to the Queen's cousin, the Earl of Harewood. Recently a vehicle was in collision with the main gates causing damage and distortion to the metalwork.



The collision has distorted the metalwork, loosening the leaded joints.



The refurbished gates. In position and resplendent in a new coat of paint.



The gates were cleaned of built-up paint layers, jigged up and straightened out.



Joints loosened in the collision were refilled with lead, the method used in the gates original construction.

